

LOT 4 INFRASTRUCTURE OVERVIEW

Water System

- Upgrade required at Hamilton Dam
- Upgrade/twinning of watermain trunk leading out from lake reservoirs
- Extensive replacements of watermain with larger diameter trunks along Windermere and Cumberland road
- Looping of watermains either along Union Road or within Trilogy's sites 5 and 6